

### **FACTS ABOUT:**

### **Globe Fireworks**

#### **Site Location**

The former Globe Fireworks site is situated on four parcels along the south side of East Old Philadelphia Road (Route 7) in a predominantly residential area approximately 0.8 mile east of the town of North East, Cecil County. There are nine dwellings with approximately 20 residents on the four parcel site. The addresses of the dwellings are 814, 830, 832, 836, 838, 842, 844, 850 and 856 East Old Philadelphia Road.

## **Site History**

A review of available records indicates that the site use was residential until sometime in the 1950s. Aerial photographs from 1938 and 1947 do not appear to show fireworks manufacturing related activities on or near the site. On June 2, 1961 a large explosion leveled five on-site buildings. Fireworks operations continued until sometime before 1977. During the years of fireworks operations on site, the name of the operating company changed immediately after large explosions. The following table chronicles the names and dates of the companies known to have operated there:

Company name	Approximate date of large explosion or file information signaling company name change
Bacon Hill Fireworks/Beacon Hill	Sometime prior to June 2, 1961
Fireworks	
Eagle Fireworks	Sometime after June 2, 1961
North East Fireworks	Sometime prior to May 23, 1963
Brooks Pyrotechnical and Chemical	Sometime after January 19, 1965
Company	
Brooks Fireworks	Sometime prior to February 3, 1965
Globe Fireworks	Sometime prior to December 17, 1968
Globe Fuse and Specialty Company	Sometime after April 23, 1971 until sometime in 1977
Interstate Fireworks Company may have operated on parcel 495 sometime prior to May 2, 1961	
until a May 1962 explosion.	

# **Environmental Investigations**

In April 2009, the Maryland Department of the Environment's Land Restoration Program (MDE) collected aqueous samples from on site and nearby residential wells and submitted them to GPL Laboratories for perchlorate analysis using EPA Method 314.0. Results of the chemical analyses did



not identify perchlorate in the residential well samples.

# **Current Status**

In April 2010, MDE completed a Site Inspection (SI) of the former Globe Fireworks site. Since the Toxicological Evaluation conducted with the data collected from the SI did not identify elevated risks, MDE recommended no further investigation of hazardous wastes from the former fireworks operations at the site.

