WELLHEAD AREA SURVEY B.S.A. CAMP POTOMAC DINING HALL - A ACHD SITE NO. 88

Oldtown, Allegany County, Maryland

ALWI Project No. AL7N001

1.0 INTRODUCTION

Advanced Land and Water, Inc. (ALWI) was retained by the Allegany County Health Department (ACHD) to prepare a Wellhead Area Survey for the Boy Scouts of America Camp Potomac Dining Hall (the Camp), located on the east side of Wilson Road in southern Allegany County, Maryland. This site, designated No. 88 by ACHD, is served by one production well completed in the local bedrock aquifer. A second well at the camp designated ACHD site no. 89 was originally surveyed but later deleted from this program by ACHD.

The draft Maryland Department of the Environment (MDE) "Transient Water Systems Operations Guidance" manual (herein termed the "Guidance Manual") defines a Non-Transient Non-Community (NTNC) Water System as one that "...serves at least 25 regular consumers over 6 months per year." An informal interview suggested that the differing groups of campers combined with the camp only being open, on a daily basis, 8 weeks out of the year suggest that this system is a transient non-community system (TNC).

1.1 Purpose

The Safe Drinking Water Act (SDWA) of 1974 required the U.S. Environmental Protection Agency (EPA) to develop enforceable drinking water quality standards to protect the public health. In 1986, amendments made to the SDWA strengthened provisions for the protection of underground sources of drinking water. These amendments included provisions for establishing Wellhead Protection Programs by individual states under "umbrella" EPA oversight. The EPA approved a statewide Wellhead Protection Program developed by MDE in June 1991.

The MDE program originally applied to community water supplies, only. A newly proposed broadening of the federal Clean Water Act will have the result of expanding the MDE Wellhead Protection Program to encompass non-community supplies both transient and non-transient in nature. ACHD, in cooperation with MDE, established this program to bring existing non-community supplies into compliance with the coming regulations.

1.2 SCOPE

ALWI prepared this Wellhead Area Survey following ACHD requirements, which followed MDE guidelines for transient system operation and wellhead protection.

- 1. Site Reconnaissance, Photographic Documentation and Interviews ALWI observed the onsite wellhead, storage, treatment, and distribution infrastructure to the degree exposed without excavation or exposure to personal hazards. ALWI used an ACHD-owned digital camera to photograph conditions surrounding the wellhead at the time of the field reconnaissance. Said photographs are stored on ACHD's computer system. ALWI interviewed the owner/operator and/or employee(s) to document information on the use patterns, history, and problems associated with the supply.
- 2. **Baseline Water Quality Assessment** ALWI purged the water system and collected samples for analysis in the ACHD laboratory that is affiliated with the Maryland Department of Health and Mental Hygiene (DHMH). ALWI performed this fieldwork in accordance with MDE potable water sampling criteria including in-field measurements of turbidity, chlorine, and pH. ACHD selected the analyte list based on countywide experience with potability concerns and the capabilities of the aforementioned laboratory. The analytes included total and fecal coliform bacteria, nitrates, nitrites, iron, sulfur and manganese (Appendix A).
- 3. **Contamination Hazard Assessment** ALWI identified existing and potential contaminant hazards within the delineated area based on visual observations and the techniques enumerated above. ALWI ranked these hazards in term of relative risk and provided concrete suggestions for their appropriate address. More generally, herein ALWI provides specific recommendations for source reduction measures, contingency plans, and other methods that may help better protect against occurrences of groundwater contamination.

2.0 HYDROGEOLOGIC FRAMEWORK

ALWI used published information from the United States Geological Survey and the Maryland Geological Survey to identify and describe the characteristics of the local hydrogeologic setting.

2.1 BEDROCK GEOLOGY

The Camp is situated within the Valley and Ridge physiographic province and is underlain by fine-grained sedimentary rock of Devonian age. The Marcellus and Needmore formations (undifferentiated) underlie the site and mainly consist of black shales (Glaser, 1994). These rocks have been folded and faulted, resulting in synclines (concave-upward folds) and anticlines (convex-upward folds).

In three dimensions, the local rock formations dip at right angles to the direction of plunge of the fold system. In general, dip directions may help govern groundwater (and contaminant) movement directions in the bedrock but plunge directions have less relation. At this location, the bedding planes dip to the east, which suggests that deep groundwater flow directions.

2.2 SAPROLITE AND SOIL MANTLE

2.2 SAPROLITE AND SOIL MANTLE

Natural chemical weathering of the shallow portion of the bedrock, due to percolating water, has chemically altered many of the original rock-forming minerals to clays and other secondary minerals. This has resulted in the development of shallow saprolite (weathered bedrock) and the overlying soil mantle. The thickness of the soil and saprolite varies considerably over short distances depending on the thickness of Quaternary alluvial deposits and other factors. In highly fractured zones, enhanced groundwater storage and movement has accelerated the breakdown of the rock-forming minerals and has caused formation of a thicker saprolitic deposit.

3

2.3 AQUIFER RECHARGE

Precipitation infiltrating through the soil and Quaternary alluvium on site and/or in up-gradient areas is the primary source of aquifer recharge to the on-site supply well. Generally, overlying soil horizons act to absorb and then slowly release infiltrating precipitation. However, in areas where fracture zones have formed, percolating groundwater can reach the water table quickly. A portion of the precipitation percolates downward through the soil mantle and then migrates through narrow, interconnected joints, fractures, faults, and cleavage planes in the bedrock.

2.4 GEOLOGY-CONTROLLED GROUNDWATER FLOW

Generally, bedding plane partings and cross-bedding fracture zones (where present) function as both downward and lateral water conduits. Consequently, such zones receive and transmit water at a rate higher than would otherwise be achievable and, accordingly, are preferential conduits for groundwater flow and contaminant transport.

3.0 WATER QUALITY ASSESSMENT

Historic water quality data for the Marcellus and Needmore formations is unavailable. At this location, ALWI collected baseline groundwater samples on December 2, 1998, in accordance with the MDE sampling procedures specified in COMAR 26.08.05. ALWI collected raw water samples as specified in COMAR 26.04.01.14.

ACHD's laboratory analyzed the samples for those constituents of countywide concern. These included total coliform bacteria as specified in COMAR 26.04.01.11A-C (alkalinity, color, conductance, hardness, iron, manganese, nitrate-nitrite nitrogen (COMAR 26.04.01.14(4)(a)), nitrite nitrogen (COMAR 26.04.01.14(4)(b)), pH, and total dissolved solids. The results are included as Appendix A, and suggest potability relative to the samples collected.

4.0 DELINEATION

ALWI delineated an area of potential concern surrounding this site's well using generalized criteria developed by MDE for non-community supplies, as modified by ALWI (with ACHD consent) based on the specific topographic setting of the site. ALWI began by using a fixed radius of 1,000 feet around the well. From this radial area, ALWI then excluded downgradient areas more than 100 feet from the wellhead as well as areas unlikely to contribute recharge to the well based on intervening streams and/or drainage divides. ALWI also excluded steeply-sloping cross-gradient areas.

The resultant delineation is shown on the "Water Plant Information" survey form (Appendix B) and encompasses approximately 90% of the circle (originally 72 acres in size) or 65 acres. Within an assumed 600 gallons per day per acre (gpd/ac) of annualized groundwater recharge (Slaughter and Darling, 1962, Table 37), slightly less than 40,000 gallons per day exists within the aquifer beneath this surveyed area. In actuality, the modest demand of this well (doubtlessly less than 1,000 gpd) is more than one full order of magnitude smaller than the total available in the surveyed area, lending a high degree of conservatism to this analysis.

Negligible nitrate-nitrogen concentrations were detected in the sample ALWI collected. This obviated the need for a nitrate balance assessment.

5.0 CONTAMINANT THREATS ASSESSMENT

ALWI performed a site reconnaissance on December 2, 1998. During the reconnaissance, local land use conditions were observed with emphasis on the potential use, storage and disposal practices of hazardous materials and petroleum products. Such conditions may have included visual evidence for present or former spills, stained or discolored ground surfaces, stressed vegetation, unusual odors, or visible underground storage tank (UST) facilities. Adjacent and nearby properties were also visually scanned for such evidence from the property and nearby public right-of-ways. Off-site properties were not entered. ALWI relied on the accuracy of an interview with the on-site ranger for this information.

5.1 POTENTIAL HAZARDS AT THE WELLHEAD

Design, construction and present condition are important factors in determining a well's susceptibility to contamination. No well tag was visible. Accordingly, ALWI could not assess the initial design nor present condition of the casing or grout seal. ALWI observed that the portion of the casing exposed at ground surface appeared intact and was equipped with a conventional pitless-style cap of the type that can sometimes allow insects to enter the well. An upgrade to a more modern cap would provide greater protection against microbial contamination.

5.2 OTHER LOCAL CONTAMINATION RISKS

ALWI observed several potential contamination sources in the delineated area, none of which appeared present to a grave or immediate concern. ALWI identified the following potential sources of contamination: above-ground storage tank (AST) used for fuel; and a nearby though downhill constructed wetlands used for wastewater disposal former on-site USTs and ASTs.

6.0 CONCLUSION AND RECOMMENDATIONS

ALWI found that the supply is potable relative to the analyses performed. No discharge to groundwater has been confirmed by any of the facilities or practices ALWI observed.

ALWI observed that the fuel oil for the facility is currently stored in two above ground storage tanks (ASTs). These ASTs appeared in good condition. ALWI recommends regular maintenance of this fuel storage and delivery system, including development of specific protocols to be employed in case of a leak or overfill. ALWI also recommends that fuels and food wastes be properly contained at all times so as to prevent uncontrolled discharges to land surface or subsurface.

7.0 SELECTED REFERENCES

- Cleaves, Emery T., Jonathan Edwards Jr. and John D. Glaser, 1968. Geologic Map of Maryland: Maryland Geologic Survey, 1:250,000.
- MDE Public Drinking Water Program, 1998, Transient Water System Operations Guidance; Guidance For Counties With Delegated Responsibilities (Draft), 45p.
- Slaughter, Turbit H. and John M. Darling, 1963, The Water Resources of Allegany and Washington Counties: Maryland Department of Geology, Mines, and Water Resources, Bulletin 24, p. 408.

NONC	OMMUNITY WATER	SUPPLY SANITARY SURVE	Y		
1. System Name: Camp Potomac	B.S.A. Camp Dining Hall.	2. WAS: 88	2. WAS: 88		
. System Information:		4. ADC Map/Grid:	5. Tax Map/Plat:		
Address: P.O. Box 212		71 S. H.	N/A		
Cumberland, Maryland			6. Population:		
Phone No.: (301) 478-5850		Regular	Regular 50		
7. Property Information:		8. No. Service Conne	8. No. Service Connections:		
Owner's Name Boy Scouts of A	America	9. Type of Facility:	9. Type of Facility:		
Address: P.O. Box 212			<u>x</u>		
Cumberland, Ma	Cumberland, Maryland		Campground		
Phone No. (301) 478-5850	The state of the s				
10. Contact Person:	11. Operator:				
Name: <u>Boy Scouts of Americ</u>	a Name:	<u></u>			
Phone No. (301) 729-1300	Cert. No				
12. Sample History (Has the syste	em had any violations?):				
Bacteria: None apparent or repo	orted	Nitrate: None apparent or reported			
	SURVEY	RESULTS			
13. Comments on System, Recom	mendations:				
ALWI found that the supply is po facilities or practices ALWI observ		ormed. No discharge to groundwater has been	confirmed by any of the		
condition. ALWI recommends regu	ular maintenance of this fuel storage fill. ALWI also recommends that	two above ground storage tanks (ASTs). These and delivery system, including development of fuels and food wastes be properly contained at	of specific protocols to be		
9					
	X				
14. Inspected by:	15. Date inspected:	16. System Vulnerability			

Protected

Vulnerable Yes (see report)

12/03/98

Mark W. Eisner

	WATER PLA	ANT INFORMATION				
17. Type of Treatment: (Check all that apply)	18. System Schematic (Pro	cess Flow):				
Disinfection Gas Chlorine: Sodium Hypochlorite Ultraviolet Radiation x Iron Removal Nitrate Removal PH Neutralizer Other Unknown	NOTE: This diagram the reconnaissance.	FLOW is a simplified schematic of operational Many water systems possess malfunction Actual treatment processes may differ, the	process flow observed or described on ning, disconnected and/or occasionally	SeT the date of		
19. System Storage:		20. Storage Capacity:	21. Untreated water san	npling tap?		
Ground Storage Elevated Storage Hydropneumatic Tankx Other		Typical Domestic	Yes <u>x</u> No			
WELL INFORMATION						
22. Well Information:	24. Well Location Diagram (1 in					
Tag Number: not visible	Sources (i.e. septic, sewer lines, structures, petroleum storage, surface water bodies, etc.):					
Year Drilled:						
Casing Depth:	Spring	MO NI	7 7			
Well Depth:	10) { 200	2 MUM				
Well Yield:	1/2 0720	2 de un		5		
Casing Height:	1000	TO VITA				
Grout Depth:	11777	· VI	Peven	62		
Pitless Adapter?	(()	24) (time	500			
Wiring OK? <u>unknown</u>	(2)///2000	M S LE	75 Fin			
Pump OK? <u>unknown</u>		Monday	630			
23. Well Type:	000	Whi.		2.		
Drilled <u>x</u> Driven		My Sold		12/11/11		
Dug						
25. Aquifer:	26. Quantity Used:	27. Well Cap:	28. Casing Diameter:	29. Casing Type:		
Name: <u>Devonian</u> GAP #:	Daily Avg (gpd) 400 Pumping Rate (gpm) unknown Hours run per day unknown		2" 4" 6" <u>x</u> Other	PVC Metal <u>x</u> Concrete		