Inspection Date: June 11, 2020 Site Name: Patapsco WWTP

Facility Address: 3501 Asiatic Ave, Curtis Bay, MD 21226



Maryland Department of Environment

Water and Science Administration Compliance Program 1800 Washington Blvd, Baltimore, MD 21230 410-537-3510

AI ID: 3076 Inspector: Ronald Wicks

Site Name: Patapsco WWTP

Facility Address: 3501 Asiatic Ave, Curtis Bay, MD 21226

County: Baltimore City

Inspection Date: June 11, 2020 Start Date/Time: June 11, 2020, 09:30 AM

End Date /Time: June 11, 2020, 02:30 PM

Media Type(s): NPDES Municipal Major Surface Water

Contact(s): Mr. Neal Jackson - Manager

NPDES Municipal Major Surface Water

Permit / Approval Numbers: 15DP0580

PAF Number: 20-2439

Site Status: Active

Site Condition: Noncompliance

Recommended Action: Close File

Inspection Reason: PAF

Evidence Collected:

Photos/Videos Taken, Visual Observation

Inspection Findings:

The Patapsco WWTP is an oxygen activated sludge treatment plant with biological aerated filters for nitrification and de-nitrification filters to meet ENR requirements. The treatment system consists of a grit removal system, mechanical screens and primary clarification, before secondary treatment. Final treatment consist of the following components: oxygen activated sludge reactors, secondary clarifiers, biological aerated filters for nitrification, de-nitrification filters, flow distribution chamber, chlorine contact chamber and cascade post aeration chamber.

On June 8, 2020, the Maryland Department of the Environment (Department) received a citizen's complaint of a spill in the area of Northridge Avenue & 4th Street in Wagner's Point, MD. The

Inspection Date: June 11, 2020 Site Name: Patapsco WWTP

Facility Address: 3501 Asiatic Ave, Curtis Bay, MD 21226


spill was traced back to the Patapsco WWTP by the investigating MDE Emergency Response Officer. The officer questioned the guard at the Patapsco WWTP guard shack. He was advised by her that the spill was raw sewage. The officer followed the spill down Asiatic Avenue to

Northbridge Avenue, to East Patapsco Avenue to Pennington Avenue ending at the ramp to I-695. Since the spill was not oil, the complaint was referred to WSA. I contacted the Patapsco WWTP, Manager, Mr. Neal Jackson on June 9, 2020. During our discussion, Mr. Jackson informed me that the spill occurred on June 8, 2020 at approximately 7:45 AM by a CAM vehicle transporting raw sewage. Mr. Jackson explained that the CAM vehicle had been overfilled with liquid and leaked raw sewage during transport from the Patapsco WWTP to the Quarantine Road Landfill.

According to Mr. Jackson, approximately 60 - 100 gallons of raw sewage leaked from the vehicle during transport. Mr. Jackson further stated that the maintenance staff immediately began the cleanup by applying an absorbent to the liquid and then removing the material from the roadway. I asked Mr. Jackson to submit a letter of explanation within 5 days of our conversation. A root cause analysis, if not already done, should be performed to evaluate the event. This analysis should focus on the transport of raw sewage and biosolids operations and how to prevent spills of this nature.


At my request Mr. Jackson sent me pictures of the affected areas after the cleanup. Please see below:

A copy of this report was emailed to Mr. Jackson.



Inspection Date: Site Name: Facility Address: June 11, 2020 Patapsco WWTP


3501 Asiatic Ave, Curtis Bay, MD 21226





Inspection Date: June 11, 2020 Site Name: Patapsco WWTP

Facility Address: 3501 Asiatic Ave, Curtis Bay, MD 21226



NPDES Municipal Major Surface Waterbegin checklist\id 1000218483 end checklist\id - Inspection Checklist

NPDES Municipal Major Surface Waterbegin checklist\id 1000218483 end checklist\id -					
Inspection Checklist					
Inspection Item	Status	Comments			
1. Does the facility have a discharge permit?	No Violations	begin checklist_item 1000218483 29787 1end			
[Environment Article §9-323(a)(1-3)]	Observed	checklist_item 1000218483 29787 AIOO 3076			
2. Is the discharge permit current?	No Violations	begin checklist_item 1000218483 29788 2end			
[Environment Article §9-328(a)(1)]	Observed	checklist item 1000218483 29788 AIOO 3076			
3. If the permit is not current, has facility	Not	begin checklist_item 1000218483 29789 3end			
applied for renewal? [Environment Article §9-328(a)(1)]	Applicable	checklist_item 1000218483 29789 AIOO 3076			
4. Does the facility operate as authorized	Not Evaluated	begin checklist_item 1000218483 29790 4end			
bytheir current permit? [COMAR		checklist_item 1000218483 29790 AIOO 3076			
26.08.04.01B(4)]					
5. Has the Permitee exceeded the permitted	Not Evaluated	begin checklist_item 1000218483 29791 5end			
capacity of the WWTP? [40 CFR Part 122		checklist_item 1000218483 29791 AIOO 3076			
Subpart C Section 122.42.(b)(1-3)]					
6. Is the number and location of discharge	Not Evaluated	begin checklist_item 1000218483 29792 6end			
points as described in the discharge permit?		checklist_item 1000218483 29792 AIOO 3076			
[Environment Article §9-331]					
7. Has permittee submitted correct name and	No Violations	begin checklist_item 1000218483 29793 7end			
address of receiving waters? [40 CFR	Observed	checklist_item 1000218483 29793 AIOO 3076			
[122.21.j(3)]					
8. Is the permittee meeting the compliance	Not Evaluated	begin checklist_item 1000218483 29794 8end			
schedule per permit requirements? [COMAR		checklist_item 1000218483 29794 AIOO 3076			
26.08.04.02-1A(3)]					

Inspection Date: Site Name: Facility Address: June 11, 2020 Patapsco WWTP 3501 Asiatic Ave, Curtis Bay, MD 21226

9. Has the operator or superintendent been	Not Evaluated	begin checklist_item 1000218483 29795 9end
certified by the Board in the appropriate		checklist_item 1000218483 29795 AIOO 3076
classification for the facility? [COMAR		
26.06.01.05A(1)]		
10. Are adequate records being maintained for	Not Evaluated	begin checklist_item 1000218483 29796 10end
the sampling date, time, and exact location;		checklist item 1000218483 29796 AIOO 3076
analysis dates and times; individual		_
performing analysis; and analytical results?		
[COMAR 26.08.04.03B(3)(a, b, c, e)]		
	Not Evaluated	begin checklist_item 1000218483 29797 11end
the analytical methods/techniques used?	Tvaluated	checklist item 1000218483 29797 AIOO 3076
[COMAR 26.08.04.03B(3)(d)]		CHECKIST_ICHI 1000210403 25757 A100 3070
	Mat Englanted	begin checklist_item 1000218483 29798 12end
	Not Evaluated	
3 years worth of monitoring records including		checklist_item 1000218483 29798 AIOO 3076
raw data and original strip chart recordings;		
calibration and maintenance records; and		
reports? [COMAR 26.08.04.03B(1)]		
13. Do lab records reflect that lab and	Not Evaluated	begin checklist_item 1000218483 29799 13end
monitoring equipment are being properly		checklist_item 1000218483 29799 AIOO 3076
calibrated and maintained? [Environment		
Article §9-331]		
14. Does the permittee/laboratory use suitable	Not Evaluated	begin checklist item 1000218483 29800 14end
QA/QC procedures and operate a formal		checklist item 1000218483 29800 AIOO 3076
quality assurance (QA) program using		_
appropriate controls? [40 CFR Part 136.7]		
15. Has the permittee submitted the	Not Evaluated	begin checklist item 1000218483 29801 15end
monitoring results on the proper Discharge	T (OV E) (MIMATON	checklist item 1000218483 29801 AIOO 3076
Monitoring Report form? [COMAR		
26.08.04.03C(1)]		
16. Do the Discharge Monitoring Reports	Not Evaluated	begin checklist item 1000218483 29802 16end
reflect permit conditions? [COMAR	Tvoi Evaluated	checklist item 1000218483 29802 AIOO 3076
26.08.04.03C]		CHECKIST_ITEM 1000218483 23802 ATOO 3070
	N (F 1 (1	1 . 1 11: 4 . 1000210402 20002 17 1
17. Has the permittee submitted these results	Not Evaluated	begin checklist_item 1000218483 29803 17end
within the allotted time electronically?		checklist_item 1000218483 29803 AIOO 3076
[COMAR 26.08.04.03C(2), 40 CFR Part		
127.16]		
	Not Evaluated	begin checklist_item 1000218483 29804 18end
maintained including:(a) stand-by power or		checklist_item 1000218483 29804 AIOO 3076
equivalent provisions available, (b) adequate		
alarm system for power or equipment failure		
available, (c) all treatments units are in		
service, . [40 CFR Part 122 Subpart C Section		
[122.41.e]		
19. Is sewage sludge managed correctly per	Out of	begin checklist item 1000218483 29805 19See narrative
permit requirements? [COMAR 26.04.06.09]	Compliance	section of this reportend checklist_item 1000218483
		29805 AIOO 3076
20. If a by-pass occurred since last inspection,	Not Evaluated	begin checklist item 1000218483 29806 20end
has the permittee submitted notice of the	The Evaluated	checklist item 1000218483 29806 AIOO 3076
by-pass within the allotted time? [40 CFR Part		2700071100 3070
122 Subpart C Section 122.41.m(4)(i)(C)]		
	Not Evoluated	hagin abaddligt itam 1000219492 20907 21 and
21. If a non-complying discharge occurred	Not Evaluated	begin checklist_item 1000218483 29807 21end
since the last inspection, was the regulatory		checklist item 1000218483 29807 AIOO 3076

Inspection Date: Site Name: Facility Address: June 11, 2020 Patapsco WWTP 3501 Asiatic Ave, Curtis Bay, MD 21226

	_	
agency notified within the allotted time? [40		
CFR Part 122 Subpart C Section 122.41.l(6)]		
22. If applicable, has the permitee complied	Not Evaluated	begin checklist_item 1000218483 29808 22end
with all special conditions of their permit?		checklist_item 1000218483 29808 AIOO 3076
[COMAR 26.08.03.07D]		
23. Have overflows occurred since the last	Not Evaluated	begin checklist_item 1000218483 29809 23end
inspection? [COMAR 26.08.10.02A]		checklist_item 1000218483 29809 AIOO 3076
24. Have records of overflows been	Not Evaluated	begin checklist_item 1000218483 29810 24end
maintained at the facility for at least five		checklist_item 1000218483 29810 AIOO 3076
years? [COMAR 26.08.10.06A-B]		
25. Are flow measuring devices properly	Not Evaluated	begin checklist_item 1000218483 29811 25end
installed and operated, calibration frequency		checklist_item 1000218483 29811 AIOO 3076
of flow meter adequate, flow measurement		
equipment adequate to handle expected ranges		
of flow? [40 CFR Part 122 Subpart C Section		
122.41.e]		
26. Are discharge monitoring points adequate	Not Evaluated	begin checklist_item 1000218483 29812 26end
for representative sampling? [Environment		checklist_item 1000218483 29812 AIOO 3076
Article §9-331(4)]		
27. Do parameters and sampling frequency	Not Evaluated	begin checklist_item 1000218483 29813 27end
meet the minimum requirements?		checklist_item 1000218483 29813 AIOO 3076
[Environment Article §9-331(4)]		
28. Does the permittee use the method of	Not Evaluated	begin checklist_item 1000218483 29814 28end
sample collection required by the permit?		checklist_item 1000218483 29814 AIOO 3076
[Environment Article §9-331(4)]		
29. Are analytical testing procedures used	Not Evaluated	begin checklist_item 1000218483 29815 29end
approved by EPA? [COMAR		checklist_item 1000218483 29815 AIOO 3076
26.08.01.02B(1)]		
	Not Evaluated	begin checklist_item 1000218483 29816 30end
used, has proper approval been obtained?		checklist_item 1000218483 29816 AIOO 3076
[COMAR 26.08.01.02B(1)]		
31. Has the permittee notified the Department	Not Evaluated	begin checklist_item 1000218483 29817 31end
of the name and address of the commercial		checklist_item 1000218483 29817 AIOO 3076
laboratory? [COMAR 26.08.04.03A(3)]		
32. Were discharges observed at the	Not Evaluated	begin checklist_item 1000218483 29818 32end
authorized outfalls? [Environment Article		checklist_item 1000218483 29818 AIOO 3076
§9-314(b)(1)]		
33. If discharges were observed, do the	Not Evaluated	begin checklist_item 1000218483 29819 33end
discharges or receiving waters have any		checklist_item 1000218483 29819 AIOO 3076
visible pollutants observed? [Environment		
Article §9-314(b)(1)]		
34. Were discharge samples collected?	Not Evaluated	begin checklist_item 1000218483 29820 34end
[Environment Article §9-261(c)(1)]	N. P. d d.	checklist item 1000218483 29820 AIOO 3076
35. Does this facility have coverage under a a	Not Evaluated	begin checklist_item 1000218483 29821 35end
NPDES stormwater discharge permit? [40		checklist_item 1000218483 29821 AIOO 3076
CFR Part 122 Subpart B Section		
122.26.(c)(1)(I)(A-B)]	N. D. S. S.	1 1 11 11 11 11 1000010 100 00000 00 1
36. If the permittee has coverage under a	Not Evaluated	-
NPDES storm water permit, has a storm water		checklist_item 1000218483 29822 AIOO 3076
pollution prevention plan been developed and		
implemented as required? [40 CFR Part 122		
Subpart B Section 122.26.(c)(1)(I)(A-B)]		

Inspection Date: Site Name: Facility Address: June 11, 2020 Patapsco WWTP

3501 Asiatic Ave, Curtis Bay, MD 21226

37. Are the permit condit [Environment Article §9-:	_	Not Evaluated	begin checklist_item 1000218483 checklist_item 1000218483 2982	
Ronald Wicks/Date ron.wicks@maryland.gov 410-537-3510				
Inspector: Ronald	d A. Wicks 6	/12/2020	Received by:	
Signature/Da	ate	_		
			Print Name	
Report Provided to:				
Report Provided to: [] Fax [x] Email	Neal Jackson			