Recent Potable Water Sample Results Table Charlies Service Station Site Oil Control Program Case #1995-1777-BA

Last Updated: July 2022

PROPERTIES WHERE SAMPLE RESULTS WERE NON-DETECT FOR ALL COMPOUNDS

ADDRESS	SAMPLE DATE
11110 LIBERTY RD	5/27/2022
11012 LIBERTY RD	5/27/2022
4509/4511 WARDS CHAPEL RD	6/7/2022
4507 CHURCHVIEW AVE	6/10/2022
11023 LIBERTY RD	7/14/2022
4513 WARDS CHAPEL RD	7/13/2022
4511 CHURCHVIEW AVE	7/13/2022
4509 CHURCHVIEW AVE	7/13/2022

PROPERTIES WITH DETECTION OF AT LEAST ONE PETROLEUM-RELATED COMPOUND					
	SAMPLE	DETECTED COMPOUND IN μg/L			
ADDRESS	DATE	MTBE	DIPE	TAME	ТВА
11024 LIBERTY RD	7/14/2022	243	4.95	ND	10.4
4507 WARDS CHAPEL RD	6/16/2022	1868	9.16	14	201
4506 CHURCHVIEW AVE	5/27/2022	0.68	ND	ND	ND
4400 POWELLS RUN RD	6/24/2022	2.7	ND	ND	ND
GROUNDWATER	20	NR	NR	NR	

PROPERTIES PENDING SANIFEE RESULTS ON OWNER REPET TO SANIFEE RECUEST	NER REPLY TO SAMPLE REQUE	OWNER	OR	RESULTS	MPLE	ING S	PEND	PERTIES	PRO
--	---------------------------	--------------	----	---------	------	-------	------	---------	-----

ADDRESS
4510 ROBOSSON RD
4506 ROBOSSON RD
11000 LIBERTY RD
10918 STEFFENY RD
10915 STEFFENY RD
4407 POWELLS RUN RD
4413 POWELLS RUN RD
10939 LIBERTY RD

NOTES:

- 4508 Churchview cannot be sampled at this time due to out of service well
- 4509 and 4511 Churchview share a well
- All sample dates are the most recent. Some properties may have been sampled more than once.
- All samples were analyzed for volatile organic compounds, including fuel oxygenates and naphthalene by EPA method 524.2. Properties with a history of onsite heating oil

use were also also analzyed for total petroleum hydrocarbons - diesel range organics by EPA method 8015

Abbreviations:

DIPE: diisopropyl ether

MTBE: methyl tertiary-butyl ether

ND: not detected above laboratory reporting limits

NR: not regulated

TAA: tertiary amyl alcohol

TAME: tertiary amyl methyl ether

TBA: tertiary butyl alcohol μ g/L: micrograms per liter